

A calibration flight was attempted, however, much of the flight was spent troubleshooting interface problems between the radar altimeter, laser altimeter, and triple-mount cameras with the computer program. Cable connections were repaired and, if weather permits, a calibration flight will be conducted on 27 August.